


Model MA150

200A AC Mini Clamp-on Meter




Additional User Manual Translations available at www.extech.com

Introduction

Thank you for selecting the Extech MA150 AC Mini Clamp Meter. This device is shipped fully tested and calibrated and, with proper use, will provide years of reliable service. Please visit our website (www.extech.com) to check for the latest version and translations of this User Manual, Product Updates, Product Registration, and Customer Support.

Meter Description

1. Current sense jaw
2. Non-contact AC voltage indicator light
3. Flashlight button
4. Rotary function switch
5. MAX hold and Backlight key
6. LCD display
7. Clamp trigger
8. MODE key
9. COM input jack
10. V Ω input jack



Safety Information



Caution! Refer to the explanation in this Manual



Double Insulation

This meter has been designed to be safe in use, but the operator must use caution in its operation. The rules listed below should be carefully followed for safe operation.


1. **NEVER** apply voltage or current to the meter that exceeds the specified maximum:
2. **USE EXTREME CAUTION** when working with voltages greater than 60VDC or 25VAC rms. These voltages are considered a shock hazard.
3. **NEVER** operate the meter unless the back cover and the battery/fuse door are in place and fastened securely.

| Input Limits | |
|------------------------------------|---------------|
| Function | Maximum Input |
| AC Current | 200A |
| AC/DC Voltage | 600V AC/DC |
| Resistance, Diode, Continuity Test | 600V AC/DC |

Operation

AC Current Measurements

- 1) Set the Function switch to the 200A AC range.
- 2) Press the jaw trigger and clamp around, fully enclosing a single conductor. Do not allow a gap between the two halves of the jaw. Refer to the diagram at right for the correct way to enclose a single conductor.
- 3) Read the ACA value on the LCD.



AC/DC Voltage Measurements

- 1) Insert the black test lead into the negative **COM** terminal and the red test lead into the positive **V** terminal.
- 2) Set the function switch to the **V** position.
- 3) Select AC or DC with the **MODE** button.
- 4) Connect the test leads in parallel to the circuit under test.
- 5) Read the voltage measurement on the LCD display.

Resistance and Continuity Measurements

- 1) Insert the black test lead into the negative **COM** terminal and the red test lead into the positive **V** Ω terminal.
- 2) Set the function switch to the Ω position.
- 3) Use the **MODE** button to select resistance. The $M\Omega$ icon will appear in the display.
- 4) Touch the test leads across the circuit or component under test. It is best to disconnect one side of the device under test so the rest of the circuit will not interfere with the resistance reading.
- 5) For Resistance tests, read the resistance on the LCD display
- 6) For Continuity, use the **MODE** button to select continuity ")". The display icons will change when the **MODE** button is pressed.
- 7) If the resistance is $<120 \Omega$ the meter's beeper will sound.

Diode Test

- 1) Insert the black test lead banana plug into the negative **COM** jack and the red test lead banana plug into the positive **V** Ω jack.
- 2) Set the function switch to the Ω position.
- 3) Press the **MODE** button to indicate on the display.
- 4) Touch the test probes to the diode under test. Forward voltage will typically indicate 0.400 to 0.700V. Reverse voltage will indicate "OL". Shorted devices will indicate near 0V and an open device will indicate "OL" in both polarities.

Non-Contact AC Voltage Detection

WARNING: Risk of Electrocution. Before use, always test the Voltage Detector on a known live circuit to verify proper operation

- 1) AC Voltage detection operates on any of the three Function switch positions.
- 2) Touch the probe tip to the hot conductor or insert into the hot side of the electrical outlet.
- 3) If AC voltage is present, the detector light will illuminate.

NOTE: The conductors in electrical cord sets are often twisted. For best results, slowly slide the probe tip along a length of the cord to assure placing the tip in close proximity to the live conductor.

NOTE: The detector is designed with high sensitivity. Static electricity or other sources of energy may randomly turn the detector light on. This is normal operation

MAX Hold

To hold the highest reading on the LCD, short press the "MAX" key. The meter reading will not change as readings change, rather it will only display the highest reading encountered since the MAX hold button was pressed. Press the MAX hold button again to return the meter to normal operation.

Backlight

Press and hold the "MAX" key for more than one second to turn the backlight on. This will also activate the MAX Hold function. To release the MAX Hold function and return the meter to normal operation, short press the "MAX" key. The backlight will automatically turn off after 15 seconds. To manually turn off the backlight, press and hold the "MAX" key for more than 1 second.

Flashlight

Press and hold the top button to turn the flashlight on. Release the button to turn the flashlight off.

Specifications

General Specifications

| | |
|------------------------|--|
| Display | 2000 count Digit LCD with white LED backlight |
| Polarity | Minus sign (-) indicates negative polarity |
| Jaw opening | 18mm (0.7") |
| Current sensor | Hall effect sensor type |
| AC Current Bandwidth | 50/60Hz |
| AC Voltage Bandwidth | 50/400Hz |
| Overload indication | "OL" displayed on the LCD |
| Display rate | 2 readings/second, nominal |
| Battery | Two 1.5V AAA batteries |
| Low Battery indication | "BATT" displayed on the LCD |
| Auto Power off | approx. 15 minutes |
| Operating conditions | 0 to 30°C (32 to 86°F) 90%RH; 30 to 40°C (86 to 104°F) 75%RH; 40 to 50°C (104 to 122°F) 45%RH |
| Storage conditions | -30 to 60°C (-14 to 140°F); < 90% Relative Humidity |
| Altitude | Operate at less than 3000 meters |
| Weight | 176g (6.2 oz.) including battery |
| Dimensions | 164 x 65 x 32mm (6.5 x 2.6 x 1.3") (HWD) |
| Standards | For indoor use and in accordance with the requirements for double insulation to IEC1010-1 (1995); EN61010-1 (1995) Overvoltage Category III 300V and Category II 600V, Pollution Degree 2. |



Range Specifications

| Function | Range | Resolution | Accuracy (of reading) |
|------------------------|--|--------------|---|
| AC Current | 200.0A | 0.1A | $\pm (2.5\% \text{ rdg} + 10 \text{ digits})$ |
| DC Voltage | 200.0mV | 0.1mV | $\pm(0.5\% \text{ rdg} + 5 \text{ digits})$ |
| | 2.000V | 1mV | $\pm(1.2\% \text{ rdg} + 3 \text{ digits})$ |
| | 20.00V | 10mV | |
| | 200.0V | 0.1V | |
| | 600V | 1V | $\pm(1.5\% \text{ rdg} + 3 \text{ digits})$ |
| AC Voltage | 2.000V | 1mV | $\pm(1.5\% \text{ rdg} + 3 \text{ digits})$ |
| | 20.00V | 10mV | |
| | 200.0V | 0.1V | |
| | 600V | 1V | $\pm(2.0\% \text{ rdg} + 4 \text{ digits})$ |
| Resistance | 200.0 Ω | 0.1 Ω | $\pm(1.0\% \text{ rdg} + 4 \text{ digits})$ |
| | 2.000k Ω | 1 Ω | $\pm(1.5\% \text{ rdg} + 2 \text{ digits})$ |
| | 20.00k Ω | 10 Ω | |
| | 200.0k Ω | 100 Ω | |
| | 2.000M Ω | 1k Ω | $\pm(2.0\% \text{ rdg} + 3 \text{ digits})$ |
| | 20.00M Ω | 10k Ω | $\pm(3.0\% \text{ rdg} + 5 \text{ digits})$ |
| Non-Contact AC Voltage | 100VAC to 600VAC 50/60Hz | | |
| Diode Test | Test current: 0.3mA typical; Open circuit voltage: 1.5VDC typical | | |
| Continuity | Threshold <120 Ω Test current <1mA | | |

Maintenance



WARNING: To avoid electrical shock, remove the test leads, disconnect the meter from any circuit and turn OFF the meter before opening the case. Do not operate with an open case.

Battery Replacement

- 1) When the low battery symbol appears on the LCD the batteries must be replaced.
- 2) Power down and remove the Phillips head screw that secures the battery compartment at the back of the meter.
- 3) Open the battery compartment and replace the two 1.5V AAA batteries observing correct polarity. Re-assemble the meter before use.

Safety: Please dispose of batteries responsibly; never dispose of batteries in a fire, batteries may explode or leak. If the meter is not to be used for 60 days or more, remove the battery and store separately.



Never dispose of used batteries or rechargeable batteries in household waste. As consumers, users are legally required to take used batteries to appropriate collection sites, the retail store where the batteries were purchased, or wherever batteries are sold.

Disposal: Do not dispose of this instrument in household waste. The user is obligated to take end-of-life devices to a designated collection point for the disposal of electrical and electronic equipment.

Copyright © 2013-2017 FLIR Systems, Inc.

All rights reserved including the right of reproduction in whole or in part in any form
ISO-9001 Certified

www.extech.com